

REPORT OF SITE VISIT

Class- Second year and Third Year (B.E.)

Date: 20/02/2016

Number of student's present- 40

Places visited- Oil pipe line at KANDLA, PLAT LOAD TEST .

Number of sites visited- 2

Undertaking by the students- attached

Faculty members accompanying students- Mr. Meet Dudiya , Ms. Srilaxmi Bokka, Ms. Vidhi Sanghvi

Facility provided by institute- Bus facility

Tiffin facility- Students had taken their Lunch at Purohit Restaurant.

Route of sites visited- 1) AVIETR to Oil pipe line site (Approx.118 km)

2) Oil pipe line to to Plat load test site (Approx.5km)

3) Plat load test site to Purohit Restaurant (Approx. 20km)

4)Purohit Restaurant to AVIETR(Approx 98 km)


Description of works/items observed/learnt at site 1(Oil pipe line at Kandla):

We reached around 12:05 A.M to there .we have seen the foundation of oil pipe line and Curing process . We also seen the Rapid Harding Concrete process on the Site.

Description of works/items observed/learnt at site 2(Plate Load Test):

We have also seen the plate load test for construction of ware houses. In that Process truss is used as load Structure and About Fix interval reading was taken by site supervisor Mr. Rajendra Kher .


23/2/16
Sign of faculty


Sign of HOD